

Reserve Fund Analysis Report

New Study with Site Visit POA of Lake Ridge Cedar Hill, TX



Report #: 9350

Inspection Date: February 26, 2019
For Year Beginning: January 1, 2020
For Year Ending: December 31, 2020
Date Prepared: April 9, 2019

Prepared by: Richard Hamilton RS, PRA

Report Status: Final-







April 9, 2019

POA of Lake Ridge 100 Lake Ridge Pkwy Cedar Hill, TX 75104

Dear Manager and Board,

We are pleased to provide you with the enclosed reserve study report for POA of Lake Ridge. This reserve study adheres to the Community Association Institute's (CAI) standards regarding service levels and disclosures.

The report has been divided into five easy-to-understand sections:

Executive Summary, provides an overview of the Association's current physical condition and financial situation, outlining significant findings and conclusions. This section of the report should be used as a quick reference in helping the reader to understand the parameters and results of the study.

Part I, Reserve Study Methodology, details the framework, methods, and materials used in developing the reserve study and the associated funding plan. This part provides a comprehensive understanding of the methodology and the process taken to develop the report.

Part II, Financial Analysis, examines report funding and results with projections for individual reserve component expenses and recommended funding.

Part III, Physical Analysis, provides in-depth, detailed condition assessments for each reserve component along with maintenance recommendations and depreciation schedules based on estimated useful life, remaining useful life and current replacement costs.

Part IV, General Information, provides a detailed explanation of the terms and definitions used within the report as well as a Frequently Asked Questions and explanation of Limitations sections.

Part V, Member's Summary, includes all the information necessary to keep your Association Members informed of the financial condition of the Association in a short, concise handout.

Three funding models are presented in detail. **Community Association Reserves recommends that the Board adopt a 100% Funding Plan whenever possible**, but a 70% Threshold alternative is included and will be presented to the Board should the current financial position of the community not allow for 100% full funding.

As you review the report and detail information, please feel free to contact our office with any questions that may arise.

Sincerely,

Richard S Hamilton RS, PRA Community Association Reserves

(214) 790-9858

info@CAReserves.com

TABLE OF CONTENTS POA of Lake Ridge

Executive Summary	E-1
PART I - RESERVE STUDY METHODOLOGY	
The Reserve Study Process	1-1
PART II - FINANCIAL ANALYSIS	
Summary of the Financial Analysis	2-1
Current Assessment Funding Summary	2-2
Current Assessment Funding Projection	2-3
100% Funding Summary	2-4
100% Component Funding Projection	2-5
70% Threshold Funding Summary	2-6
70% Threshold Funding Projection	2-7
Baseline Funding Summary	2-8
Baseline Funding Projection	2-9
Funding Comparison by Percent Funded (Chart)	2-10
Funding Reserve Ending Balance Comparison (Chart)	2-11
Annual Expenses VS Funding Assessment (Chart)	2-12
Annual Projects Detail	2-13
Annual Expenditure Spreadsheet	2-18
PART III - COMPONENT ANALYSIS	
Inventory Summary Report	3-1
Inventory by Remaining Life	3-2
Asset Index	3-4
Component Inventory Detail	3-6
PART IV - GENERAL INFORMATION	
Implementing Your Study	4-1
General Information and FAQ's	4-3
Definitions of Terms Used	4-6

TABLE OF CONTENTS POA of Lake Ridge

Disclosures and Limitations	4-9
PART V - MEMBER'S SUMMARY	
	5-1
Member's Summary Member's Inventory Summary	5-1 5-2

Executive Summary

Purpose of Reserve Study

The purpose of this study is to provide the Association with an inventory of reserve components that require periodic repair and replacement and a reserve funding plan to offset the associated costs of these projects. This report provides condition assessments and maintenance schedules for each reserve component to assist the association in making budget decisions regarding reserve funding.

The Board of Directors has a fiduciary responsibility to maintain and preserve the value of common area assets belonging to the entity. As part of their fiduciary duty, board members are responsible for the long-term planning and funding of future major repairs and replacements of community assets.

This reserve study adheres to the Community Association Institute's (CAI) standards regarding service levels and disclosures. This report complies with The American Institute of Certified Public Accountants (AICPA) guidelines for Common Interest Realty Associations. Recommendations and accompanying assumptions are the results of information provided to Community Association Reserves (CAR) and assembled for the Association's use.

Community Description:

POA of Lake Ridge is a Master Association, developed in approximately 1989. The community consists of a community center, park assets, entrance monuments, a marina, lakes and common space. The community is in overall good condition and appears well maintained.

Summary of the Reserve Study

The study provides an overview of the Association's current physical condition and financial situation, outlining significant findings and conclusions. It details the framework, methods, and materials used in developing the reserve study and the associated funding plan. The Financial Analysis examines the findings and results with projections for individual reserve component expenses and recommended funding. The Physical Analysis provides an in-depth, detailed condition assessment for each reserve component along with maintenance recommendations based on the estimated useful life (UL), remaining useful life (RUL) and current replacement costs.

Association Information:

Association Name:	POA of Lake Ridge
Association Location:	Cedar Hill, TX
Association Type:	Master Association
Number of Units:	2114
Report Period:	2020 - 2049
Inspection Date:	February 26, 2019

Economic Information:

Annual Inflation Rate for this Report:	2.80%
Annual Interest on Funds for this Report:	1.50%
Annual Increase to Contribution:	3.50%
Reserve Beginning Balance:	\$120,100

Fully Funded Reserve Balance:	\$372,103
Current Percent Funded:	32%
Current Contribution:	\$12,000 annually

Reserve Funding Status:

Your fund status position is **Weak**. Your association has achieved this status because your current percent funded (your reserve fund bank balance divided by your fully funded balance) is **32%**. Reserve funds are generally classified into three categories: "weak" at 0% to 30% funded, "fair" at 31% to 69% funded and "strong" if your funding is 70% or above. Percent funded is a measurement of risk to the association members. Risk includes: a large increase in dues, a special assessment to the members, or loss in home value due to deterioration or loss of community assets.

Our recommendation is generally a 100% funding plan which means that for every dollar of deterioration that occurs within a community, the current membership - those that benefit directly from that asset, will place a dollar in the bank to offset that cost. This is the "fairest" method of funding, as a lower percentage will place a higher burden on a future membership when a replacement is due.

Plan Funding Recommendations:

Plan	Contribution	Contribution	Ending	Special
Option	annually	Per Unit	% Funded	Assessment
Current Plan	\$12,000	\$5.68	-169%	None
100% Funding	\$58,700	\$27.77	100%	None
70% Funding	\$54,000	\$25.54	70%	None
Baseline Funding	\$49,900	\$23.60	42%	None

Five (5) Year Snapshot:

Plan	Annual	Annual	Ending Cash	Ending Percent	Special
Year	Contribution	Expenditures	Balance	Funded	Assessment
2020	\$58,700	\$42,450	\$138,395	35%	None
2021	\$60,754	\$9,159	\$192,840	43%	None
2022	\$62,881	\$15,234	\$244,095	48%	None
2023	\$65,082	\$0	\$313,814	54%	None
2024	\$67,360	\$48,999	\$337,157	56%	None

An Important Note Regarding Expense Cycling:

As the Board reviews the report and projected expenses, notice that several components are denoted as "partial" or "part" replacements. This indicates that this particular component has been "cycled" and is not scheduled for full replacement. This may be the result of similar components that were placed in service at different times, or in many cases, a long-lived component that would not otherwise be reflected in the replacement projections. An example of this would be concrete, which typically has a useful life of 50-75 years, and may not otherwise be reflected in a 30-year projection window.

It is important to understand that cycling serves as a flag to the Board as well as future Boards that the component is accumulating funds. Those funds may or may not be necessary when the cycle ends. Since cost projections are based on the total life of a component, it is important that if funds are not needed at the end of a

financials indicating that that	at portion of the cyc	led amount has bee	en spent.	

PART I RESERVE STUDY METHODOLOGY

The Reserve Study Process

A Reserve Study is the art and science of anticipating, and preparing for, an association's major common area repair and replacement expenses. Partially art, because we are making projections about the future. Partially science, because the work is a combination of research and well- defined computations, following consistent National Reserve Study Standards.

The foundation of this and every Reserve Study is your Reserve Component List (the items that you are reserving for). This is because the Reserve Component List defines the *scope and schedule* of all your anticipated upcoming Reserve projects. Based on that List and your starting balance, we calculate the association's Reserve Fund Strength (reported in terms of "Percent Funded"). Then we compute a Reserve Funding Plan to provide for the Reserve needs of the association. These form the results of your Reserve Study.

It is important to keep in mind that reserve contributions are not "for the future". Reserve contributions are designed to offset the ongoing, daily deterioration of your Reserve assets. Done well, a stable, budgeted Reserve Funding Plan will collect sufficient funds from the owners who enjoyed the use of those assets, so the association is financially prepared for the irregular expenditures scattered through future years when important assets eventually require replacement.

The Component Analysis

Determination of what constitutes a reserve component is dependent on a number of factors. A four-part test is generally used to distinguish a reserve item from an operational or maintenance expense. A component is included as a reserve item only if it satisfies ALL criteria outlined below:

- It is the Association's responsibility to maintain.
- It has a predictable useful service life.
- Its useful life fits within the projection period.
- Its cost for repair or replacement meets a pre-determined threshold amount.

The components that an Association includes in its reserve funding plan are also dependent on the type of project, the construction properties and the Association's applicable governing documents and state statutes.

Component Useful Life

The useful life of a reserve component relates to the number of years it is expected to last, given reasonable care and maintenance. The prediction of reserve and building component life can be no more than an informed estimate based upon information made available at the time of the site visit. Consideration is given to vendor recommendations, material warranty information provided at the time of the report's development, along with other published sources. The data and service life estimates in this report are based on information gathered from various groups and industry sources as outlined below:

- Historical data from the Association;
- Community Managers, Board Members and Service Personnel;
- Manufacturer recommendations and industry standards;
- Published sources of service life data;
- Manufacturers and suppliers' data.

Component Remaining Useful Life

The remaining life of a reserve component refers to the number of years left before an item's expected repair or replacement. A component's remaining life is contingent upon the following factors:

- Age/years in service;
- Physical condition;
- Frequency and quality of inspections and maintenance;
- General use:
- Environment, impact of weather and building location;
- Installation methods that meets or exceed industry standards;
- Design and quality of materials used.

In addition to deterioration or anticipated failure of a component, the longevity may be impacted by obsolescence. The accuracy of the estimate is contingent upon reliable information made available at the time of the report. It is important to note that even with the highest degree of diligence and experience, outcomes will vary, and no guarantee can be given as to the timing or service life of the reserve components. All service life assessments in this report are based on the assumption that maintenance is carried out in accordance with manufacturer's recommendations and installation instructions, together with industry standards of workmanship. Consideration is given to visible design and signs of improper installation of components that will have an impact upon the anticipated service life of the component.

The Financial Analysis

An Association, like any business entity, must prepare financially for the replacement and repair of its assets. Reserve study funding analysis is an important part of the annual budget process. Reserve funding should be reviewed at least once annually to help determine the annual assessment to be charged to members. The following elements are used in the financial analysis.

Recommended Funding Rate. We advocate a program of regular reserve fund contributions and promote a gradual means of reserving for future repair and replacement expenses. Recommended contributions are set at a level where they require only minor annual increases. The rate is designed to distribute the anticipated cost of common property ownership equitably between all members over the entire projection period.

Fully Funded Balance. The Fully Funded balance is equal to the total depreciated cost of all the Association's reserve components. It is determined by dividing each reserve component's cost by its useful life, and multiplying that by the number of years the component has been in service (effectively its age). The recommendations in this report are based upon a Fully Funded plan, which sets the goal of achieving one hundred percent fully funded reserves by the end of the 30-year projection period. We recommend full funding as we feel that this approach best provides a solid platform to address future needs, thus dramatically reducing the need for special assessments or major contribution increases.

Percent Funded. An Association's reserve fund status is assessed by comparing the ratio of actual or projected funds available versus how much they should have saved. The result is presented as a percentage and is commonly known as "percent funded". Percent funded is calculated by dividing the Association's current reserve fund balance by the fully funded balance. This equation is an industry measure of how well prepared an Association is to meet its current and future repair and replacement obligations. Percent funded highlights the strength of the association's reserve account in relation to the anticipated costs of repair and replacement.

Reserve Component Cost. Current cost estimates for reserve components are derived from a variety of

sources but typically are based on the latest local vendor pricing acquired from regional contractors and suppliers. When needed, additional information and cost data is sourced from national construction estimators. All cost estimates formulated from national estimators are based upon the latest specific geographical information for the area. Future cost estimates are determined by applying the assumed annual inflation rate to the current cost of each component.

Inflation Rate. The effect of inflation on the cost of reserve components is a key factor in the financial projections. Historically, the cost of construction materials and labor rise at a higher rate than that experienced by the general economy. We have chosen to use an inflationary multiplier that is somewhat higher than the current general consumer index for inflation. The rate used is based upon the historical average of inflation over the last 30 years. This rate reflects a realistic appreciation of future costs for reserve components and assists the Association in adequately budgeting for increasing cost.

Interest Rate. The interest rate used in this report is formulated on a conservative rate of return. Unless otherwise advised by the Association, an assumed net interest rate of 1.00% is used. We offer no guarantee or opinion in relation to investment decisions made by the Association or the rate of return achieved.

Current Reserve Fund Balance. The analysis, recommendations, and financial projections made within this report are heavily reliant on information provided by the Association and its representatives. The starting reserve fund balance (current or projected) and member contribution totals are supplied by these sources. This information has not been audited nor have the financial projections or recommendations.

Reserve Plan Goals

According to National Reserve Study Standards, there are four Funding Principles to balance in developing your Reserve Funding Plan.

- Our first objective is to design a plan that provides you with sufficient cash to perform your Reserve projects in a timely manner.
- Second, a stable contribution is recommended because it keeps these naturally irregular expenses from unsettling the budget.
- Reserve contributions that are evenly distributed over current and future owners enables each owner to pay their fair share of the association's Reserve expenses over the years.
- And finally, we develop a plan that is fiscally responsible and safe for Board members to recommend to their association.

Remember, it is the Board's duty to provide for the ongoing care of the common areas. Board members invite liability exposure when Reserve contributions are inadequate to offset ongoing common area deterioration.

The Reserve Funding Plan must provide adequate funds when they are expected to be required at a future point in time. If \$100,000 is needed in five years for a new roof, the Funding Plan should yield a Reserve Balance of at least \$100,000 in that year. Because associations are corporations and their members expect and deserve the corporation to be run in a stable manner, it is important that the budget be designed for year to year stability. Large assessment changes from year to year indicate instability,

and homeowners deserve a degree of stability in order to plan their own budgets.

Reserve Funding and Risk

Reserve adequacy is not measured in cash terms. Reserve adequacy is determined when the *amount* of current Reserve cash is compared to Reserve component deterioration (the *needs of the association*). Having *enough* means the association can execute its projects in a timely manner with existing Reserve funds. *Not having *enough* typically creates deferred maintenance, large increases in assessments, special assessments or a loss in property value.

Adequacy is measured in a two-step process:

- Calculate the *value of deterioration* at the association (called Fully Funded Balance, or FFB).
- Compare that to the Reserve Fund Balance and expressed as a percentage.

Each year, the *value of deterioration* at the association changes. When there is more deterioration (as components approach the time they need to be replaced), there should be more cash to offset that deterioration and prepare for the expenditure. Conversely, the *value of deterioration* shrinks after projects are accomplished. The *value of deterioration* (the FFB) changes each year, and is a moving but predictable target.

There is a high risk of special assessments and deferred maintenance when the Percent Funded is *weak*, below 30%. Approximately 30% of all associations are in this high-risk range. While the 100% point is Ideal (indicating Reserve cash is equal to the *value of deterioration*), a Reserve Fund in the 70% -130% range is considered strong (low risk of special assessment).

Measuring your Reserves by Percent Funded tells how well prepared your association is for upcoming Reserve expenses.

PART II FINANCIAL ANALYSIS

Summary of the Financial Analysis

Current Fully Funded Balance: \$372,102.57 Current Reserve Fund Balance: \$120,100.00

Current Percent Funded: 32%

Current Contribution Annually: \$12,000.00 Per Unit: \$5.68

There are three basic funding strategies from which most associations select. It is recommended that associations consult professionals to determine the best strategy or combination of plans that best suit the association's need. Additionally, associations should consult with their financial advisor to determine the tax implications of selecting a particular plan. Further, consult with the American Institute of Certified Public Accountants (AICPA) for their reporting requirements.

The three funding plans and descriptions of each are detailed below. Associations will need to update their reserve studies more or less frequently depending on the funding strategy they select.

• Full funding (Recommended) — The goal of this funding strategy is to attain and maintain the reserves at or near 100 percent. For example, if an association has a component with a 10-year life and a \$10,000 replacement cost, it should have \$3,000 set aside for its replacement after three years (\$10,000 divided by 10 years=\$1,000 per year X 3 years=\$3,000). In this case, \$3,000 equals full funding.

Target Contribution Annually: \$58,700.00 Per Unit: \$27.77

• Threshold funding (Alternative) — This method is based on the baseline funding concept. The minimum reserve cash balance in threshold funding; however, is set at a predetermined percentage of the required dollar amount. We will generally attempt to place the association funding between 65% and 75% funded, which will place them in a "strong" funding position. Using the previous example, if an association has a component with a 10-year life and a \$10,000 replacement cost, it should have \$3,000 set aside for its replacement after three years to achieve 100% funding. In the case of a 70% funding threshold, \$2,100 (\$3,000 x 70%) would need to be set aside to achieve the funding goal.

Target Contribution Annually: \$54,000.00 Per Unit: \$25.54

• Baseline funding (Not Recommended) —The goal of this funding method is to keep the reserve cash balance above zero. This means that while each individual component may not be fully funded, the reserve balance does not drop below zero during the projected period. An association using this funding method must understand that even a minor reduction in a component's remaining useful life can result in a deficit in the reserve cash balance. Associations can implement this funding method more safely by conducting annual reserve updates that include field observations.

Target Contribution Annually: \$49,900.00 Per Unit: \$23.60

It is up to the Board to select a plan that best suits the association and its long term goals. For comparison purposes, we have included a **Current Assessment Funding** plan, which is a projection of the association's financial health based on the plan in place without modification. This can be a base of comparison when selecting a plan. It may also demonstrate why change is needed.

POA of Lake Ridge

Cedar Hill, TX

Current Assessment Funding Summary

Report Date	April 9, 2019
Account Number	9350
Version	1.0
Budget Year Beginning	January 1, 2020
Budget Year Ending	December 31, 2020
Total Units	2114
Phase Development	1 of 1

Report Parameters	
Inflation Annual Assessment Increase Interest Rate on Reserve Deposit	2.80% 3.00% 1.50%
2020 Beginning Balance	\$120,100

Current Assessment Funding Summary

This is the community's **current funding plan**, based upon your current Reserve Contribution. This analysis will be used as a base comparison to the Fully Funded plan (100% Funding) and the Threshold plan (70% Funding) to offer a comparison of the study results and their effects upon the community and contributions.

In this summary, we have used the current level of Reserve Contributions and completed a full 30-year analysis based upon our component findings.

Current Assessment Funding Model Summary of Calculations	
Required Annual Contribution	\$12,000.00
\$5.68 per unit annually	
Average Net Annual Interest Earned	\$1,344.75
Total Annual Allocation to Reserves	\$13,344.75
\$6.31 per unit annually	

POA of Lake Ridge Current Assessment Funding Projection

Beginning Balance: \$120,100

2.8	.g =	,100		Projected	Fully	
	Annual	Annual	Annual	Ending	Funded	Percent
Year	Contribution	Interest	Expenditur	_	Reserves	Funded
			r			
2020	12,000	1,345	42,450	90,995	393,404	23%
2021	12,360	1,413	9,159	95,608	451,051	21%
2022	12,731	1,397	15,234	94,502	505,638	19%
2023	13,113	1,614		109,229	579,026	19%
2024	13,506	1,106	48,999	74,842	605,756	12%
2025	13,911		131,310	-42,557	550,325	
2026	14,329		134,544	-162,772	491,769	
2027	14,758		52,673	-200,687	517,539	
2028	15,201		2,494	-187,980	597,466	
2029	15,657		11,424	-183,746	672,355	
2030	16,127		173,982	-341,602	584,189	
2031	16,611		169,369	-494,360	500,308	
2032	17,109		38,883	-516,134	550,288	
2033	17,622			-498,511	643,764	
2034	18,151		57,959	-538,319	682,462	
2035	18,696		131,459	-651,083	648,932	
2036	19,256		163,335	-795,162	584,005	
2037	19,834		207,687	-983,014	474,042	
2038	20,429		18,083	-980,668	558,353	
2039	21,042		50,698	-1,010,324	614,007	
2040	21,673		99,458	-1,088,108	623,674	
2041	22,324			-1,065,784	738,506	
2042	22,993		26,464	-1,069,256	832,074	
2043	23,683			-1,045,573	958,270	
2044	24,394		93,855	-1,115,034	994,398	
2045	25,125		105,428	-1,195,336	1,022,602	
2046	25,879		471,573	-1,641,030	678,244	
2047	26,655		91,507	-1,705,881	718,081	
2048	27,455		14,084	-1,692,510	841,843	
2049	28,279			-1,664,231	986,855	

POA of Lake Ridge Cedar Hill, TX

100% Funding Summary

Report Date	April 9, 2019
Account Number	9350
Version	1.0
Budget Year Beginning	January 1, 2020
Budget Year Ending	December 31, 2020
Total Units	2114
Phase Development	1 of 1

Report Parameters	
Inflation Annual Assessment Increase Interest Rate on Reserve Deposit	2.80% 3.50% 1.50%
2020 Beginning Balance	\$120,100

100% Funding Summary

The 100% funding plan, also called the fully funded plan, is based upon the "fairest" funding method. This plan anticipates that for each dollar of deterioration that occurs within the community, the current membership that is benefiting from those assets will place one dollar in the bank to offset that deterioration.

This analysis is our recommended funding level. It will present the least risk to the association members and ensure a strong financial position in the future.

100% Funding Model Summary of Calculations	
Required Annual Contribution	\$58,700.00
\$27.77 per unit annually Average Net Annual Interest Earned	\$2,045.25
Total Annual Allocation to Reserves \$28.73 per unit annually	\$60,745.25

POA of Lake Ridge 100% Component Funding Projection

Beginning Balance: \$120,100

2.8	.g =	100		Projected	Fully	
	Annual	Annual	Annual	Ending	Funded	Percent
Year	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
			1			
2020	58,700	2,045	42,450	138,395	393,404	35%
2021	60,754	2,850	9,159	192,840	451,051	43%
2022	62,881	3,607	15,234	244,095	505,638	48%
2023	65,082	4,638		313,814	579,026	54%
2024	67,360	4,983	48,999	337,157	605,756	56%
2025	69,717	4,133	131,310	279,698	550,325	51%
2026	72,157	3,260	134,544	220,571	491,769	45%
2027	74,683	3,639	52,673	246,219	517,539	48%
2028	77,297	4,815	2,494	325,837	597,466	55%
2029	80,002	5,916	11,424	400,331	672,355	60%
2030	82,802	4,637	173,982	313,788	584,189	54%
2031	85,700	3,452	169,369	233,571	500,308	47%
2032	88,700	4,251	38,883	287,639	550,288	52%
2033	91,804	5,692		385,135	643,764	60%
2034	95,017	6,333	57,959	428,526	682,462	63%
2035	98,343	5,931	131,459	401,341	648,932	62%
2036	101,785	5,097	163,335	344,888	584,005	59%
2037	105,347	3,638	207,687	246,187	474,042	52%
2038	109,035	5,057	18,083	342,196	558,353	61%
2039	112,851	6,065	50,698	410,414	614,007	67%
2040	116,801	6,416	99,458	434,173	623,674	70%
2041	120,889	8,326		563,388	738,506	76%
2042	125,120	9,931	26,464	671,973	832,074	81%
2043	129,499	12,022		813,494	958,270	85%
2044	134,031	12,805	93,855	866,476	994,398	87%
2045	138,722	13,497	105,428	913,268	1,022,602	89%
2046	143,578	8,779	471,573	594,052	678,244	88%
2047	148,603	9,767	91,507	660,915	718,081	92%
2048	153,804	12,010	14,084	812,645	841,843	97%
2049	159,187	14,577		986,409	986,855	100%

POA of Lake Ridge

Cedar Hill, TX

70% Threshold Funding Summary

Report Date	April 9, 2019
Account Number	9350
Version	1.0
Budget Year Beginning	January 1, 2020
Budget Year Ending	December 31, 2020
Total Units	2114
Phase Development	1 of 1

Report Parameters	
Inflation Annual Assessment Increase	2.80% 3.50%
Interest Rate on Reserve Deposit	1.50%
2020 Beginning Balance	\$120,100

70% Funding Summary

The 70% funding plan, also called the threshold funded plan, is based upon a modified funding method. This plan anticipates that for each dollar of deterioration that occurs within the community, the current membership that is benefiting from those assets will place seventy cents in the bank to offset that deterioration.

This analysis is **an alternative funding level** which seeks to keep the association in a strong financial position, but does present a bit of risk. If components experience a failure earlier than anticipated due to influences outside of the community's control (such as workmanship or weather) the members may be placed in a position where a special assessment is required to make repairs. It also pushes a portion of deterioration down the road to a membership that has not fully benefited from a particular asset.

70% Threshold Funding Model Summary of Calculations	
Required Annual Contribution	\$54,000.00
\$25.54 per unit annually Average Net Annual Interest Earned	\$1,974.75
Total Annual Allocation to Reserves	\$55,974.75
\$26.48 per unit annually	

POA of Lake Ridge 70% Threshold Funding Projection

Beginning Balance: \$120,100

J				Projected	Fully	
	Annual	Annual	Annual	Ending	Funded	Percent
Year	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
2020	54,000	1,975	42,450	133,625	393,404	34%
2021	55,890	2,705	9,159	183,061	451,051	41%
2022	57,846	3,385	15,234	229,058	505,638	45%
2023	59,871	4,334		293,263	579,026	51%
2024	61,966	4,593	48,999	310,823	605,756	51%
2025	64,135	3,655	131,310	247,304	550,325	45%
2026	66,380	2,687	134,544	181,827	491,769	37%
2027	68,703	2,968	52,673	200,824	517,539	39%
2028	71,108	4,042	2,494	273,479	597,466	46%
2029	73,596	5,035	11,424	340,686	672,355	51%
2030	76,172	3,643	173,982	246,519	584,189	42%
2031	78,838	2,340	169,369	158,329	500,308	32%
2032	81,598	3,016	38,883	204,059	550,288	37%
2033	84,454	4,328		292,841	643,764	45%
2034	87,410	4,834	57,959	327,125	682,462	48%
2035	90,469	4,292	131,459	290,427	648,932	45%
2036	93,635	3,311	163,335	224,038	584,005	38%
2037	96,912	1,699	207,687	114,963	474,042	24%
2038	100,304	2,958	18,083	200,142	558,353	36%
2039	103,815	3,799	50,698	257,058	614,007	42%
2040	107,449	3,976	99,458	269,025	623,674	43%
2041	111,209	5,704		385,937	738,506	52%
2042	115,102	7,119	26,464	481,693	832,074	58%
2043	119,130	9,012		609,836	958,270	64%
2044	123,300	9,589	93,855	648,870	994,398	65%
2045	127,615	10,066	105,428	681,123	1,022,602	67%
2046	132,082	5,124	471,573	346,757	678,244	51%
2047	136,705	5,879	91,507	397,834	718,081	55%
2048	141,489	7,879	14,084	533,118	841,843	63%
2049	146,441	10,193		689,753	986,855	70%

POA of Lake Ridge

Cedar Hill, TX

Baseline Funding Summary

Report Date	April 9, 2019
Account Number	9350
Version	1.0
Budget Year Beginning	January 1, 2020
Budget Year Ending	December 31, 2020
Total Units	2114
Phase Development	1 of 1

Report Parameters	
Inflation Annual Assessment Increase Interest Rate on Reserve Deposit	2.80% 3.50% 1.50%
Contingency	3.00%
2020 Beginning Balance	\$120,100

Baseline Funding Summary

The baseline funding plan is a modified funding method and it is generally **NOT recommended** that the community embark upon this program.

This analysis is <u>an alternative funding level</u> which seeks to keep the reserve fund from dropping below zero at any point in time over the course of the study period. This plan present significant risk. If components experience the smallest failure earlier than anticipated, or repair or replacement pricing is greater than anticipated, the members will be placed in a position where a special assessment is

required to make repairs.

This plan should only be used for associations that are severely underfunded as a temporary stepping stone into a more stable plan.


Baseline Funding Model Summary of Calculations			
Required Annual Contribution	\$49,900.00		
\$23.60 per unit annually			
Average Net Annual Interest Earned	<u>\$1,913.25</u>		
Total Annual Allocation to Reserves	\$51,813.25		
\$24.51 per unit annually			

POA of Lake Ridge Baseline Funding Projection

Beginning Balance: \$120,100


J	,			Projected	Fully	
	Annual	Annual	Annual	Ending	Funded	Percent
Year	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
2020	49,900	1,913	42,450	129,463	405,571	32%
2021	51,646	2,579	9,159	174,530	465,001	38%
2022	53,454	3,191	15,234	215,941	521,276	41%
2023	55,325	4,069		275,335	596,934	46%
2024	57,261	4,254	48,999	287,851	624,491	46%
2025	59,266	3,237	131,310	219,044	567,345	39%
2026	61,340	2,188	134,544	148,028	506,979	29%
2027	63,487	2,383	52,673	161,224	533,545	30%
2028	65,709	3,367	2,494	227,805	615,944	37%
2029	68,009	4,266	11,424	288,655	693,150	42%
2030	70,389	2,776	173,982	187,838	602,256	31%
2031	72,852	1,370	169,369	92,691	515,782	18%
2032	75,402	1,938	38,883	131,149	567,307	23%
2033	78,041	3,138		212,328	663,674	32%
2034	80,773	3,527	57,959	238,669	703,569	34%
2035	83,600	2,862	131,459	193,672	669,002	29%
2036	86,526	1,753	163,335	118,615	602,067	20%
2037	89,554	7	207,687	490	488,703	0%
2038	92,689	1,126	18,083	76,223	575,622	13%
2039	95,933	1,822	50,698	123,279	632,997	19%
2040	99,290	1,847	99,458	124,959	642,963	19%
2041	102,766	3,416		231,140	761,346	30%
2042	106,362	4,666	26,464	315,704	857,808	37%
2043	110,085	6,387		432,176	987,907	44%
2044	113,938	6,784	93,855	459,043	1,025,152	45%
2045	117,926	7,073	105,428	478,615	1,054,229	45%
2046	122,053	1,936	471,573	131,031	699,220	19%
2047	126,325	2,488	91,507	168,338	740,290	23%
2048	130,747	4,275	14,084	289,275	867,879	33%
2049	135,323	6,369		430,967	1,017,377	42%

POA of Lake Ridge Funding Comparison by Percent Funded (Chart)




The chart above compares the three funding plans (Current Assessment Funding, Threshold Funding and 100% Component Funding) by the percent funded over 30 years. This allows your association to view and then choose the funding model that might best fit your community's needs.

POA of Lake Ridge Funding Reserve Ending Balance Comparison (Chart)



The chart above compares the projected annual reserve fund ending balances for the three funding plans (Current Assessment Funding, Threshold Funding and 100% Component Funding) over the 30 year period.

POA of Lake Ridge Annual Expenses VS Funding Assessment (Chart)



The Annual Expenditures graph demonstrates how the plan seeks to "flatten out" the periodic spikes that occur over time. This aids the Association in proper budget planning while ensuring funds are available to meet the future financial needs.

Description	Expenditures
Replacement Year 2020	
Concrete Parking - Replace	26,250
Concrete Sidewalks - Replace	3,000
Deck - Restain	9,000
BBQ Equipment - Replace	1,650
Park Furnishings - Replace (partial)	2,550
Total for 2020	\$42,450
Replacement Year 2021	
Metal Fence/Rail - Paint	9,159
Total for 2021	\$9,159
	4,72
Replacement Year 2022	
Concrete Trail - Refurbish (partial)	6,251
Office Equipment - Replace	2,642
Exterior Masonry - Repoint	4,227
Gravel Walking Trail - Refurbish (partial)	2,114
Total for 2022	\$15,234
No Replacement in 2023	
Replacement Year 2024	
Exterior Surfaces - Repaint	5,026
Interior Surfaces - Repaint	5,584
Wood Bridges - Repair	38,390
Total for 2024	\$48,999
Replacement Year 2025	
Concrete Parking - Replace	30,137
Concrete Sidewalks - Replace	3,444
Deck Substructure - Repair	5,740
Miscellaneous Signs - Refurbish (part)	4,592
Exterior Lighting - Replace	2,870
HVAC Units - Replace (partial)	19,287
Office Carpet - Replace Office Deck - Replace	10,820 28,300
Rental Floor Carpet - Replace	26,118
Total for 2025	\$131,310

Description	Expenditures
Replacement Year 2026 Deck - Restain Panda Class (Maintain	10,622
Ponds - Clean/Maintain Security Equipment - Replace	118,021 5,901
Total for 2026	\$134,544
Replacement Year 2027	
Concrete Trail - Refurbish (partial)	7,176
Office Equipment - Replace	3,033
Irrigation System - Replace (partial)	18,199
Trees/Vegetation - Replace (partial)	24,265
Total for 2027	\$52,673
Replacement Year 2028	
Storm Drainage - Maintain	2,494
Total for 2028	\$2,494
Replacement Year 2029	
Metal Fence/Rail - Paint	11,424
Total for 2029	\$11,424
Replacement Year 2030	
Concrete Parking - Replace	34,599
Concrete Sidewalks - Replace	3,954
BBQ Equipment - Replace	2,175
Park Furnishings - Replace (partial)	3,361
Meeting Room Furniture - Replace (part) Office Furniture - Replace	3,559 3,954
Vinyl Rail Fence - Replace	17,398
Kitchen - Refurbish	26,361
Phone System - Replace	9,226
Windows/Doors - Replace	69,395
Total for 2030	\$173,982
Replacement Year 2031	
Pond Dam Walls - Maintain	169,369
Total for 2031	\$169,369

Replacement Year 2032 Concrete Trail - Refurbish (partial) 8,239	
Concrete Trail - Refurbish (partial) 8,239	
	9
Office Equipment - Replace 3,482	
Deck - Restain 12,536	5
Exterior Surfaces - Repaint 6,268	3
Exterior Masonry - Repoint 5,572	2
Gravel Walking Trail - Refurbish (partial) 2,786	5
Total for 2032 \$38,883	3
No Replacement in 2033	
Replacement Year 2034	
Interior Surfaces - Repaint 7,360	\mathbf{C}
Wood Bridges - Repair 50,600	\mathbf{C}
Total for 2034 \$57,959	9
Replacement Year 2035	
Concrete Parking - Replace 39,722)
Concrete Sidewalks - Replace 4,540	
Deck Substructure - Repair 7,566	
Miscellaneous Signs - Refurbish (part) 6,053	
Lobby Furniture - Replace 30,264	
Interior Bathrooms, Fixtures - Refurbish 10,592	
Kitchen Appliances - Replace 3,783	
Tile Flooring - Replace 28,940	C
Total for 2035 \$131,459	9
Replacement Year 2036	
Ponds - Clean/Maintain 155,557	7
Security Equipment - Replace 7,778	
Total for 2036 \$163,335	- 5
Replacement Year 2037	
Concrete Trail - Refurbish (partial) 9,459	9
Office Equipment - Replace 3,998	
Metal Fence/Rail - Paint 14,248	
Irrigation System - Replace (partial) 23,983	
Trees/Vegetation - Replace (partial) 31,983	
Metal Fence - Replace 105,542	

Description	Expenditures
Replacement Year 2037 continued	
Metal Rail - Replace	18,470
Total for 2037	\$207,687
Replacement Year 2038	
Deck - Restain	14,795
Storm Drainage - Maintain	3,288
Total for 2038	\$18,083
Replacement Year 2039	
Monument Sign - Refurbish	50,698
Total for 2039	\$50,698
Replacement Year 2040	
Concrete Parking - Replace	45,603
Concrete Sidewalks - Replace	5,212
Exterior Surfaces - Repaint	7,818
BBQ Equipment - Replace	2,866
Park Furnishings - Replace (partial)	4,430
Exterior Lighting - Replace	4,343
HVAC Units - Replace (partial)	29,186
Total for 2040	\$99,458
No Replacement in 2041	
Replacement Year 2042	
Concrete Trail - Refurbish (partial)	10,859
Office Equipment - Replace	4,590
Exterior Masonry - Repoint	7,344
Gravel Walking Trail - Refurbish (partial)	3,672
Total for 2042	\$26,464
No Replacement in 2043	
Replacement Year 2044	
Deck - Restain	17,461
Interior Surfaces - Repaint	9,701
Wood Bridges - Repair	66,693
Total for 2044	\$93,855

Description	Expenditures
Replacement Year 2045	
Concrete Parking - Replace	52,355
Concrete Sidewalks - Replace	5,983
Metal Fence/Rail - Paint	17,771
Deck Substructure - Repair	9,972
Miscellaneous Signs - Refurbish (part)	7,978
Meeting Room Furniture - Replace (part)	5,385
Office Furniture - Replace	5,983
Total for 2045	\$105,428
Replacement Year 2046	
Ponds - Clean/Maintain	205,032
Security Equipment - Replace	10,252
Pond Dam Walls - Maintain	256,290
Total for 2046	\$471,573
Replacement Year 2047	
Concrete Trail - Refurbish (partial)	12,467
Office Equipment - Replace	5,269
Irrigation System - Replace (partial)	31,616
Trees/Vegetation - Replace (partial)	42,155
Total for 2047	\$91,507
Replacement Year 2048	
Exterior Surfaces - Repaint	9,750
Storm Drainage - Maintain	4,333
Total for 2048	\$14,084

	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
Beginning Balance Annual Assessment Interest Earned	120,100 58,700 2,045	138,395 60,754 2,850	192,840 62,881 3,607	244,095 65,082 4,638	313,814 67,360 4,983	337,157 69,717 4,133	279,698 72,157 3,260	220,571 74,683 3,639	246,219 77,297 4,815	325,837 80,002 5,916
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	42,450 393,404 35% 138,395	9,159 451,051 43% 192,840	15,234 505,638 48% 244,095	579,026 54% 313,814	48,999 605,756 56% 337,157	131,310 550,325 51% 279,698	134,544 491,769 45% 220,571	52,673 517,539 48% 246,219	2,494 597,466 55% 325,837	11,424 672,355 60% 400,331
Description										
Deck Substructure - Repair Office Deck - Replace						5,740 28,300				
Deck - Restain Metal Roof Roof - Replace	9,000						10,622			
Windows/Doors - Replace Interior Surfaces - Repaint					5,584					
Exterior Surfaces - Repaint Exterior Masonry - Repoint			4,227		5,026					
Tile Flooring - Replace Rental Floor Carpet - Replace						26,118				
Office Carpet - Replace Kitchen - Refurbish						10,820				
Kitchen Appliances - Replace Interior Bathrooms, Fixtures - Refurbish										
Lobby Furniture - Replace Meeting Room Furniture - Replace (part)										
Phone System - Replace Office Equipment - Replace			2,642				5 001	3,033		
Security Equipment - Replace Office Furniture - Replace						10.207	5,901			
HVAC Units - Replace (partial) Metal Fence - Replace						19,287				
Metal Rail - Replace Metal Fence/Rail - Paint		9,159								11,424
Vinyl Rail Fence - Replace Exterior Lighting - Replace						2,870				
Monument Sign - Refurbish										

	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029
Description										
Miscellaneous Signs - Refurbish (part)						4,592				
Irrigation System - Replace (partial)								18,199		
Trees/Vegetation - Replace (partial)								24,265		
Pond Dam Walls - Maintain										
Ponds - Clean/Maintain							118,021			
Storm Drainage - Maintain									2,494	
BBQ Equipment - Replace	1,650									
Park Furnishings - Replace (partial)	2,550									
Gravel Walking Trail - Refurbish (partial)			2,114							
Concrete Trail - Refurbish (partial)			6,251					7,176		
Wood Bridges - Repair					38,390					
Concrete Parking - Replace	26,250					30,137				
Concrete Sidewalks - Replace	3,000					3,444				
Year Total:	42,450	9,159	15,234		48,999	131,310	134,544	52,673	2,494	11,424

	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039
Beginning Balance	400,331	313,788	233,571	287,639	385,135	428,526	401,341	344,888	246,187	342,196
Annual Assessment	82,802	85,700	88,700	91,804	95,017	98,343	101,785	105,347	109,035	112,851
Interest Earned	4,637	3,452	4,251	5,692	6,333	5,931	5,097	3,638	5,057	6,065
Expenditures	173,982	169,369	38,883		57,959	131,459	163,335	207,687	18,083	50,698
Fully Funded Reserves	584,189	500,308	550,288	643,764	682,462	648,932	584,005	474,042	558,353	614,007
Percent Fully Funded	54%	47%	52%	60%	63%	62%	59%	52%	61%	67%
Ending Balance	313,788	233,571	287,639	385,135	428,526	401,341	344,888	246,187	342,196	410,414
Description										
Deck Substructure - Repair						7,566				
Office Deck - Replace										
Deck - Restain			12,536						14,795	
Metal Roof Roof - Replace										
Windows/Doors - Replace	69,395									
Interior Surfaces - Repaint					7,360					
Exterior Surfaces - Repaint			6,268							
Exterior Masonry - Repoint			5,572			• • • • • •				
Tile Flooring - Replace						28,940				
Rental Floor Carpet - Replace										
Office Carpet - Replace Kitchen - Refurbish	26.261									
	26,361					2 792				
Kitchen Appliances - Replace Interior Bathrooms, Fixtures - Refurbish						3,783 10,592				
Lobby Furniture - Replace						30,264				
Meeting Room Furniture - Replace (part)	3,559					30,204				
Phone System - Replace	9,226									
Office Equipment - Replace	7,220		3,482					3,998		
Security Equipment - Replace			3,102				7,778	3,770		
Office Furniture - Replace	3,954						7,770			
HVAC Units - Replace (partial)	2,521									
Metal Fence - Replace								105,542		
Metal Rail - Replace								18,470		
Metal Fence/Rail - Paint								14,248		
Vinyl Rail Fence - Replace	17,398									
Exterior Lighting - Replace										
Monument Sign - Refurbish										50,698

	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039
Description										
Miscellaneous Signs - Refurbish (part)						6,053				
Irrigation System - Replace (partial)								23,987		
Trees/Vegetation - Replace (partial)								31,983		
Pond Dam Walls - Maintain		169,369								
Ponds - Clean/Maintain							155,557			
Storm Drainage - Maintain									3,288	
BBQ Equipment - Replace	2,175									
Park Furnishings - Replace (partial)	3,361									
Gravel Walking Trail - Refurbish (partial)			2,786							
Concrete Trail - Refurbish (partial)			8,239					9,459		
Wood Bridges - Repair					50,600					
Concrete Parking - Replace	34,599					39,722				
Concrete Sidewalks - Replace	3,954					4,540				
Year Total:	173,982	169,369	38,883		57,959	131,459	163,335	207,687	18,083	50,698

	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049
Beginning Balance	410,414	434,173	563,388	671,973	813,494	866,476	913,268	594,052	660,915	812,645
Annual Assessment	116,801	120,889	125,120	129,499	134,031	138,722	143,578	148,603	153,804	159,187
Interest Earned	6,416	8,326	9,931	12,022	12,805	13,497	8,779	9,767	12,010	14,577
Expenditures	99,458		26,464		93,855	105,428	471,573	91,507	14,084	006055
Fully Funded Reserves	623,674	738,506	832,074	958,270	994,398	1,022,602	678,244	718,081	841,843	986,855
Percent Fully Funded	70%	76%	81%	85%	87%	89%	88%	92%	97%	100%
Ending Balance	434,173	563,388	671,973	813,494	866,476	913,268	594,052	660,915	812,645	986,409
Description										
Deck Substructure - Repair						9,972				
Office Deck - Replace										
Deck - Restain					17,461					
Metal Roof Roof - Replace										
Windows/Doors - Replace										
Interior Surfaces - Repaint	- 010				9,701					
Exterior Surfaces - Repaint	7,818		5 2 4 4						9,750	
Exterior Masonry - Repoint			7,344							
Tile Flooring - Replace										
Rental Floor Carpet - Replace Office Carpet - Replace										
Kitchen - Refurbish										
Kitchen Appliances - Replace										
Interior Bathrooms, Fixtures - Refurbish										
Lobby Furniture - Replace										
Meeting Room Furniture - Replace (part)						5,385				
Phone System - Replace						,				
Office Equipment - Replace			4,590					5,269		
Security Equipment - Replace							10,252			
Office Furniture - Replace						5,983				
HVAC Units - Replace (partial)	29,186									
Metal Fence - Replace										
Metal Rail - Replace						10.001				
Metal Fence/Rail - Paint						17,771				
Vinyl Rail Fence - Replace	4 2 4 2									
Exterior Lighting - Replace	4,343									
Monument Sign - Refurbish										

	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049
Description										
Miscellaneous Signs - Refurbish (part)						7,978				
Irrigation System - Replace (partial)								31,616		
Trees/Vegetation - Replace (partial)								42,155		
Pond Dam Walls - Maintain							256,290			
Ponds - Clean/Maintain							205,032			
Storm Drainage - Maintain									4,333	
BBQ Equipment - Replace	2,866									
Park Furnishings - Replace (partial)	4,430									
Gravel Walking Trail - Refurbish (partial)			3,672							
Concrete Trail - Refurbish (partial)			10,859					12,467		
Wood Bridges - Repair					66,693					
Concrete Parking - Replace	45,603					52,355				
Concrete Sidewalks - Replace	5,212					5,983				
Year Total:	99,458		26,464		93,855	105,428	471,573	91,507	14,084	

PART III

PHYSICAL ANALYSIS

The following pages contain descriptions of each identified reserve component maintained by the association. Each reserve component is shown with its estimated useful life, remaining life, and current cost to replace. Supporting information is included where applicable.

This information is analyzed by computer to produce the cash flow analysis and funding plans.

This component inventory and condition assessment information was obtained during an on-site visit on February 26, 2019 and via subsequent discussions with local contractors, board members or agents for the board. No destructive testing was done to determine the condition of the components that are not readily accessible (for example, sampling plumbing lines or flat roof core samples).

Remaining life estimates are based on typical useful life expectancy minus effective age of components (which may not be the same as chronological age). Published costs and life expectancies may also be used. No representation is made as to how much actual costs and actual life expectancies at the time of future replacement may differ from estimates contained herein. Because actual contractor bids vary considerably, it is entirely possible that the association may select a bid that is more costly or less costly than the estimates provided. Also note that contractor estimates discussed on the following pages are not to be interpreted as formal bids or as an endorsement of that particular contractor.

This on-site inspection is not to be considered as a project audit or quality inspection.

POA of Lake Ridge Inventory Summary Report

Report Date Beginning Fiscal Year Account Number April 09, 2019 January 01, 2020 9350

Version Number 1.0

	A SOSE	*	\$	The .	Astrony Section	iningo	Ŕĸ	رمخ
Description	Sol Top	Catalogia Catalogia	\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		?" Q	idille Garage	Outrality .	Jih Jih
Deck Substructure - Repair	2025	5,000	10	0	5	5,740	1 @	5,000.00
Office Deck - Replace	2025	24,650	25	0	5	28,300	2900 @	8.50
Deck - Restain	2020	9,000	6	0	0	9,000	2000 @	4.50
Metal Roof Roof - Replace	2057	70,200	40	0	37	195,021	3900 @	18.00
Windows/Doors - Replace	2030	52,650	40	0	10	69,395	81 @	650.00
Interior Surfaces - Repaint	2024	5,000	10	0	4	5,584	1 @	5,000.00
Exterior Surfaces - Repaint	2024	4,500	8	0	4	5,026	1 @	4,500.00
Exterior Masonry - Repoint	2022	4,000	10	0	2	4,227	1 @	4,000.00
Tile Flooring - Replace	2035	19,125	35	0	15	28,940	850 @	22.50
Rental Floor Carpet - Replace	2025	22,750	25	0	5	26,118	350 @	65.00
Office Carpet - Replace	2025	9,425	25	0	5	10,820	145 @	65.00
Kitchen - Refurbish	2030	20,000	30	0	10	26,361	1@	20,000.00
Kitchen Appliances - Replace	2035	2,500	25	0	15	3,783	1@	2,500.00
Interior Bathrooms, Fixtures - Refur	2035	7,000	25	0	15	10,592	2@	3,500.00
Lobby Furniture - Replace	2035	20,000	20	0	15	30,264	1@	20,000.00
Meeting Room Furniture - Replace (2030	2,700	15	0	10	3,559	1@	2,700.00
Phone System - Replace	2030	7,000	30	0	10	9,226	1@	7,000.00
Office Equipment - Replace	2022	2,500	5	0	2	2,642	1@	2,500.00
Security Equipment - Replace	2026	5,000	10	0	6	5,901	1@	5,000.00
Office Furniture - Replace	2030	3,000	15	0	10	3,954	1@	3,000.00
HVAC Units - Replace (partial)	2025	16,800	15	0	5	19,287	6 @	5,600.00
Metal Fence - Replace	2037	66,000	40	0	17	105,542	1650 @	40.00
Metal Rail - Replace	2037	11,550	40	0	17	18,470	330 @	35.00
Metal Fence/Rail - Paint	2021	8,910	8	0	1	9,159	1980 @	4.50
Vinyl Rail Fence - Replace	2030	13,200	20	0	10	17,398	600 @	22.00
Exterior Lighting - Replace	2025	2,500	15	0	5	2,870	1@	2,500.00
Monument Sign - Refurbish	2039	30,000	20	0	19	50,698	1@	30,000.00
Miscellaneous Signs - Refurbish (part)	2025	4,000	10	0	5	4,592	1@	4,000.00
Irrigation System - Replace (partial)	2027	15,000	10	0	7	18,199	1@	15,000.00
Trees/Vegetation - Replace (partial)	2027	20,000	10	0	7	24,265	1@	20,000.00
Pond Dam Walls - Maintain	2031	125,000	15	0	11	169,369		125,000.00
Ponds - Clean/Maintain	2026	100,000	10	0	6	118,021	5 @	40,000.00
Storm Drainage - Maintain	2028	2,000	10	0	8	2,494	1@	2,000.00
BBQ Equipment - Replace	2020	1,650	10	0	0	1,650	6 @	550.00
Park Furnishings - Replace (partial)	2020	2,550	10	0	0	2,550	6 @	850.00
Gravel Walking Trail - Refurbish (p	2022	2,000	10	0	2	2,114	1@	2,000.00
Concrete Trail - Refurbish (partial)	2022	5,915	5	0	2	6,251	9100 @	6.50
Wood Bridges - Repair	2024	34,375	10	0	4	38,390	1250 @	27.50
Concrete Parking - Replace	2020	26,250	5	0	0		25000 @	10.50
Concrete Sidewalks - Replace	2020	3,000	5	0	0	3,000	1@	3,000.00

POA of Lake Ridge Inventory by Remaining Life

Description	Remaining Life	Replacement Year	Fully Funded Reserves
BBQ Equipment - Replace	0	2020	1,650
Park Furnishings - Replace (partial)	0	2020	2,550
Concrete Sidewalks - Replace	0	2020	3,000
Deck - Restain	0	2020	9,000
Concrete Parking - Replace	0	2020	26,250
Metal Fence/Rail - Paint	1	2021	7,796
Office Equipment - Replace	2	2022	1,500
Gravel Walking Trail - Refurbish (partial)	2	2022	1,600
Exterior Masonry - Repoint	2	2022	3,200
Concrete Trail - Refurbish (partial)	2	2022	3,549
Exterior Surfaces - Repaint	4	2024	2,250
Interior Surfaces - Repaint	4	2024	3,000
Wood Bridges - Repair	4	2024	20,625
Exterior Lighting - Replace	5	2025	1,667
Miscellaneous Signs - Refurbish (part)	5	2025	2,000
Deck Substructure - Repair	5	2025	2,500
Office Carpet - Replace	5	2025	7,540
HVAC Units - Replace (partial)	5	2025	11,200
Rental Floor Carpet - Replace	5	2025	18,200
Office Deck - Replace	5	2025	19,720
Security Equipment - Replace	6	2026	2,000
Ponds - Clean/Maintain	6	2026	40,000
Irrigation System - Replace (partial)	7	2027	4,500
Trees/Vegetation - Replace (partial)	7	2027	6,000
Storm Drainage - Maintain	8	2028	400
Meeting Room Furniture - Replace (part)	10	2030	900
Office Furniture - Replace	10	2030	1,000
Phone System - Replace	10	2030	4,667
Vinyl Rail Fence - Replace	10	2030	6,600
Kitchen - Refurbish	10	2030	13,333
Windows/Doors - Replace	10	2030	39,487
Pond Dam Walls - Maintain	11	2031	33,333
Kitchen Appliances - Replace	15	2035	1,000
Interior Bathrooms, Fixtures - Refurbish	15	2035	2,800
Lobby Furniture - Replace	15	2035	5,000
Tile Flooring - Replace	15	2035	10,929
Metal Rail - Replace	17	2037	6,641
Metal Fence - Replace	17	2037	37,950
Monument Sign - Refurbish	19	2039	1,500
Metal Roof Roof - Replace	37	2057	5,265

POA of Lake Ridge Inventory by Remaining Life

Description	Remaining	Replacement	Fully Funded
1	Life	Year	Reserves

POA of Lake Ridge Asset Index

Description	Replacement	Page
Deck Substructure - Repair	2025	3-6
Office Deck - Replace	2025	3-7
Deck - Restain	2020	3-8
Metal Roof Roof - Replace	2057	3-9
Windows/Doors - Replace	2030	3-10
Interior Surfaces - Repaint	2024	3-11
Exterior Surfaces - Repaint	2024	3-12
Exterior Masonry - Repoint	2022	3-13
Tile Flooring - Replace	2035	3-14
Rental Floor Carpet - Replace	2025	3-15
Office Carpet - Replace	2025	3-16
Kitchen - Refurbish	2030	3-17
Kitchen Appliances - Replace	2035	3-18
Interior Bathrooms, Fixtures - Refurbish	2035	3-19
Lobby Furniture - Replace	2035	3-20
Meeting Room Furniture - Replace (part)	2030	3-21
Phone System - Replace	2030	3-22
Office Equipment - Replace	2022	3-23
Security Equipment - Replace	2026	3-24
Office Furniture - Replace	2030	3-25
HVAC Units - Replace (partial)	2025	3-26
Metal Fence - Replace	2037	3-27
Metal Rail - Replace	2037	3-28
Metal Fence/Rail - Paint	2021	3-29
Vinyl Rail Fence - Replace	2030	3-30
Exterior Lighting - Replace	2025	3-31
Monument Sign - Refurbish	2039	3-32
Miscellaneous Signs - Refurbish (part)	2025	3-33
Irrigation System - Replace (partial)	2027	3-34
Trees/Vegetation - Replace (partial)	2027	3-35
Pond Dam Walls - Maintain	2031	3-36
Ponds - Clean/Maintain	2026	3-37
Storm Drainage - Maintain	2028	3-38
BBQ Equipment - Replace	2020	3-39
Park Furnishings - Replace (partial)	2020	3-40
Gravel Walking Trail - Refurbish (partial)	2022	3-41
Concrete Trail - Refurbish (partial)	2022	3-42
Wood Bridges - Repair	2024	3-43
Concrete Parking - Replace	2020	3-44

POA of Lake Ridge Asset Index

Description	Replacement	Page
Concrete Sidewalks - Replace	2020	3-45
Total Funded Assets	40	
Total Unfunded Assets	_0	
Total Assets	40	

Deck Substructure - Repair

Quantity 1 Allowance
Asset Cost \$5,000.00
Percent Replacement
Future Cost \$5,740.31

General Common Area

Placed in Service January 2015
Useful Life 10
Replacement Year 2025
Remaining Life 5





The deck substructure consists of metal and wood framing attached metal columns. The frame is showing signs of rust and deterioration in some areas. We anticipate an ongoing program of truss and post replacement to maintain deck integrity.

Office Deck - Replace

Quantity 2,900 GSF
Asset Cost \$24,650.00
Percent Replacement 100%
Future Cost \$28,299.74

General Common Area

Placed in Service
Useful Life
25
Replacement Year
Remaining Life
5
January 2000
25
5







The wooden deck surface located at the upper deck (1,648 GSF), lower deck (1,075 GSF) and walkway (176 GSF), located at the community center is in overall fair condition with noted weathering of the wood sealer. Recommend repairing any trip/fall hazards immediately as noticed and inspect regularly for any damage. Reseal regularly to mitigate any subsurface moisture which will accelerate deterioration. Funding is to replace all decking at one time to maintain consistency and appearance.

Deck - Restain

Quantity 2,000 GSF
Asset Cost \$9,000.00
Percent Replacement 100%
Future Cost \$9,000.00

Painting, Exterior
Placed in Service
Useful Life
Replacement Year
Remaining Life
Painting, Exterior
January 2014
2020
0





The wood decking surface sealer located at the community center appears in overall fair to poor condition with noted areas of fading or missing sealer. Recommend periodic inspections to ensure proper maintenance, repair any damage, and verify if deterioration is consistent with expectations. Seal regularly to prevent moisture penetration which will accelerate deterioration.

Metal Roof Roof - Replace

Quantity 3,900 GSF
Asset Cost \$70,200.00
Percent Replacement 100%
Future Cost \$195,021.43

Roofing
Placed in Service
Useful Life
Replacement Year
Remaining Life
Roofing
January 2017
40
2057





The corrugated metal roof on the clubhouse appears in overall good condition and is reported to have been replaced in 2017. Recommend yearly inspections by a qualified roofer to ensure proper maintenance, repair any damage, and verify if deterioration is consistent with expectations.

Windows/Doors - Replace

Quantity 81 Each
Asset Cost \$52,650.00
Percent Replacement 100%
Future Cost \$69,395.21

Placed in Service
Useful Life
Replacement Year
Remaining Life

Building Exterior
January 1990
2030
10





The (81) Windows, including the 54-window mosaic at the rear of the building, and (7) doors appear to be in overall good condition. We assume windows were installed without defect and include sufficient underlying waterproofing details. As routine maintenance, we recommend regular professional inspections. Repair as needed to ensure good weather seal and help prevent structural damage. With ordinary care and maintenance, plan to replace windows at roughly the time frame indicated. Note: for pricing, we have counted each set of double doors as two doors each.

Interior Surfaces - Repaint

Quantity 1 Allowance
Asset Cost \$5,000.00
Percent Replacement
Future Cost \$5,583.96

Painting, Interior
Placed in Service
Useful Life
Replacement Year
Remaining Life
Painting, Interior
January 2014
2024
4





Interior walls are painted and in good condition. Anticipate repairing and repainting to ensure a quality appearance.

Exterior Surfaces - Repaint

Quantity 1 Allowance
Asset Cost \$4,500.00
Percent Replacement
Future Cost \$5,025.57

	Painting, Exterior
Placed in Service	January 2016
Useful Life	8
Replacement Year	2024
Remaining Life	4



Paint is in generally good condition with minimal areas showing signs of fading, peeling, dry and missing or cracked caulking. Recommend caulking around areas of wood to brick transition. Preventing moisture penetration via cracks (wood shrinking around transitions) is key in ensuring a full useful life.

Exterior Masonry - Repoint

Quantity 1 Allowance
Asset Cost \$4,000.00
Percent Replacement
Future Cost \$4,227.14

Placed in Service
Useful Life
Replacement Year
Remaining Life

Building Exterior
January 2012
2022
2022



The brick veneer siding appears in overall good condition with no noted areas of damage or missing grout, but one small area of cracked brick, possibly from foundation movement. Recommend periodic inspections to ensure proper maintenance, repair any damage, and verify if deterioration is consistent with expectations. Repoint brick periodically to prevent subsurface moisture penetration which will accelerate the deterioration of this component.

Tile Flooring - Replace

Quantity	850 GSF
Asset Cost	\$19,125.00
Percent Replacement	100%
Future Cost	\$28,939.98

	Building Interior
Placed in Service	January 2000
Useful Life	35
Replacement Year	2035
Remaining Life	15



The tile flooring utilized throughout the clubhouse is in good condition. Floor should be cleaned, polished and sealed periodically to maintain appearance and to maximize useful life. Funding anticipates eventual replacement due to age and changes in design tastes.

Rental Floor Carpet - Replace

Quantity 350 GSY
Asset Cost \$22,750.00
Percent Replacement 100%
Future Cost \$26,118.42

Placed in Service
Useful Life
Replacement Year
Remaining Life

Building Interior
January 2000
25
25
2025
5



The rental area hallway and common area carpet, which includes the stairs and turret, is a typical medium grade commercial carpet and is in worn and stained condition in areas. Recommend regular cleaning to maximize useful life.

Office Carpet - Replace

Quantity 145 GSY
Asset Cost \$9,425.00
Percent Replacement 100%
Future Cost \$10,820.49

Placed in Service
Useful Life
Replacement Year
Remaining Life

Building Interior
January 2000
25
25
2025
5





Commercial grade carpet used throughout the office, conference and lobby areas appears in overall fair condition with some areas of stains or damage. Carpet should be shampooed periodically to ensure maximum useful life.

Kitchen - Refurbish

Quantity 1 Allowance
Asset Cost \$20,000.00
Percent Replacement
Future Cost \$26,360.95

Placed in Service
Useful Life
Replacement Year
Remaining Life

Building Interior
January 2000
2030
2030
10



Kitchen appears in good overall condition. Allowance is to replace 40 SF hard surface countertops and 10 LF of wood cabinets due to use and age.

Kitchen Appliances - Replace

Quantity 1 Allowance
Asset Cost \$2,500.00
Percent Replacement
Future Cost \$3,783.00

	Building Interior
Placed in Service	January 2010
Useful Life	25
Replacement Year	2035
Remaining Life	15



Kitchen appliances are in overall good condition. Inventory includes: (2) refrigerators and (1) microwave. Funding anticipates eventual replacement with similar quality items due to age and use.

Interior Bathrooms, Fixtures - Refurbish

Quantity 2 Each
Asset Cost \$7,000.00
Percent Replacement 100%
Future Cost \$10,592.41

	Building Interior
Placed in Service	January 2010
Useful Life	25
Replacement Year	2035
Remaining Life	15



The main center area bathrooms are decorative in design and are in good condition. Bathrooms have painted walls with tile floors and hard surface countertops. Refurbishment includes paint, replacement of counters, fixtures and interior lights.

Lobby Furniture - Replace

Quantity 1 Allowance
Asset Cost \$20,000.00
Percent Replacement 100%
Future Cost \$30,264.03

	Furnishings
Placed in Service	January 2015
Useful Life	20
Replacement Year	2035
Remaining Life	15







Approximately (15) pieces of furnishings are located in the lobby area. These include couches, chairs, tables and lamps. Commercial grade furnishings can vary widely in cost. We have used mid grade pricing. Funding anticipates periodic replacement of furnishings to maintain the appearance and appeal of the community center.

Furnishings

Meeting Room Furniture - Replace (part)

Quantity 1 Sets
Asset Cost \$2,700.00
Percent Replacement 100%
Future Cost \$3,558.73

January 2015
15
2030
10



General meeting and party room furniture inventory includes: (1) conference table; (10) chairs and (1) TV monitor. Funding anticipates replacing the furnishings on a regular basis due to wear and use.

Phone System - Replace

Quantity 1 Each
Asset Cost \$7,000.00
Percent Replacement 100%
Future Cost \$9,226.33

Placed in Service
Useful Life
Replacement Year
Remaining Life

Building Interior
January 2000
2030
2030



The office phone system appears to be in operational condition, with no reported problems. Multi-line systems have evolved rapidly over recent years with hosted PBX systems gaining popularity due to the reduced equipment costs. We have factored a hybrid system which incorporates some switching equipment hosted locally and requiring the purchase of handset equipment. The current system will need eventual replacement due to the lack of availability of parts.

Office Equipment - Replace

Quantity 1 Allowance
Asset Cost \$2,500.00
Percent Replacement
Future Cost \$2,641.96

Furnishings
Placed in Service
Useful Life
SReplacement Year
Remaining Life
Furnishings
January 2017
2022
2022





The computer equipment is used throughout the office area. Equipment appears to be in overall good condition and operating properly. Funding anticipates replacement due to age and changes in technologies.

Security Equipment - Replace

Quantity 1 Each
Asset Cost \$5,000.00
Percent Replacement 100%
Future Cost \$5,901.04

Placed in Service January 2016
Useful Life 10
Replacement Year 2026
Remaining Life 6





The security monitoring system was reportedly refurbished in 2016. Anticipate regular upgrades and replacements to this system to maintain safety/security as well as for changes in technology.

Furnishings

Office Furniture - Replace

Quantity 1 Allowance
Asset Cost \$3,000.00
Percent Replacement
Future Cost \$3,954.14

	i ui iiisiiiiigs
Placed in Service	January 2015
Useful Life	15
Replacement Year	2030
Remaining Life	10





Furniture located in the office areas are in good condition. Inventory includes: (3) desks, (3) bookcases, (10) chairs and (1) file cabinet. Anticipate replacing pieces on a regular cycle to maintain property's appearance and aesthetics. Furnishings should have an extended useful life. Funding anticipates replacing pieces of furniture (approximately 50%) as needed with no anticipation of replacing all furnishings at one time. Due to use, furnishings will wear at differieng rates.

HVAC Units - Replace (partial)

Quantity 6 Each
Asset Cost \$16,800.00
Percent Replacement 50%
Future Cost \$19,287.45

Building Mechanical

Placed in Service
Useful Life
T5
Replacement Year
Remaining Life
January 2010
2025
5







The gas furnaces are located in the rental floor area and appear to be in overall good condition with install dates ranging from 2000 to 2016. Recommend regular service in accordance with manufacturer's guidelines to ensure full useful life. Funding anticipates continued replacement of units an an as needed basis with no anticipation of replacing all units at one time.

Metal Fence - Replace

Quantity 1,650 LF
Asset Cost \$66,000.00
Percent Replacement 100%
Future Cost \$105,542.38

Placed in Service January 1997
Useful Life 40
Replacement Year 2037
Remaining Life 17







Metal is in fair condition with limited signs of rust or damage, but some broken welds. Fence has a powder coated finish that once damaged will require restoring and protecting surface from moisture. Due to prohibitive costs of removing fence to re-powder coat, funding is based on maintaining fence by treating rust and painting. Recommend periodic inspections to identify and treat damaged areas in order to avoid additional future costs to repair.

Metal Rail - Replace

Quantity 330 LF
Asset Cost \$11,550.00
Percent Replacement 100%
Future Cost \$18,469.92

Placed in Service January 1997
Useful Life 40
Replacement Year 2037
Remaining Life 17



Metal railing provides fall protection at the upper and lower clubhouse deck. Metal is in good to fair condition with limited signs of rust or damage. Metal has a powder coated finish that once damaged will require restoring and protecting surface from moisture. Due to prohibitive costs of removing rail to re-powder coat, funding is based on maintaining metal surfaces by treating rust and painting. Recommend periodic inspections to identify and treat damaged areas in order to avoid additional future costs to repair.

Metal Fence/Rail - Paint

Quantity 1,980 LF
Asset Cost \$8,910.00
Percent Replacement 100%
Future Cost \$9,159.48

Painting, Exterior
Placed in Service
Useful Life
Replacement Year
Remaining Life
Painting, Exterior
January 2013
2021





Metal fence and railing surface appears in overall fair to poor condition. Metal surfaces have a powder coated finish that once damaged will require restoring and protecting surface from moisture. Due to prohibitive costs of removing metal to re-powder coat, funding anticipates regular cycles of paint, utilizing a high quality exterior metal surface product. Remove rust and apply a rust inhibitor prior to painting.

Vinyl Rail Fence - Replace

Quantity 600 LF
Asset Cost \$13,200.00
Percent Replacement 100%
Future Cost \$17,398.23

Placed in Service January 2010
Useful Life 20
Replacement Year 2030
Remaining Life 10





Vinyl rail fence is used to accent the parking area at Ridge View Park. Vinyl fence is in good condition with minimal signs of warped or damaged rails. Recommend periodic inspections to identify and treat damaged areas in order to avoid additional future costs to repair.

Exterior Lighting - Replace

Quantity 1 Allowance
Asset Cost \$2,500.00
Percent Replacement
Future Cost \$2,870.16

Placed in Service
Useful Life
Replacement Year
Remaining Life
Lighting, Exterior
January 2010
2025
5





Light inventory includes ground, recessed and wall mounted fixtures. Anticipate replacing items on an as-needed basis with no anticipation of replacing all items at one time.

Monument Sign - Refurbish

Quantity 1 Each
Asset Cost \$30,000.00
Percent Replacement 100%
Future Cost \$50,697.95

Gene	eral Common Area
Placed in Service	January 2019
Useful Life	20
Replacement Year	2039
Remaining Life	19



A new monument and entrance sign is scheduled to be installed in 2019. Anticipate repairing or refurbishing stonework and landscape areas on a cyclical basis with no anticipation of replacing the complete sign. Funding is based on drawings and plans as well as installation estimates.

Miscellaneous Signs - Refurbish (part)

Quantity 1 Allowance
Asset Cost \$4,000.00
Percent Replacement
Future Cost \$4,592.25

General Common Area
Placed in Service January 2015
Useful Life 10
Replacement Year 2025
Remaining Life 5





Signs are a combination of stone and concrete and provide information and park names. Signs are in good to fair condition overall. Anticipate repairing or refurbishing signs on a cyclical basis with no anticipation of replacing all signs at one time.

Irrigation System - Replace (partial)

Quantity 1 Allowance
Asset Cost \$15,000.00
Percent Replacement
Future Cost \$18,198.81

Landscape and Equipment Placed in Service January 2017

Useful Life 10
Replacement Year 2027
Remaining Life 7





Irrigation system is typically repaired on an as-needed basis as part of the landscape contract. Occasionally, extensive repair and replacement of large sections of the irrigation system are necessary as provided herein. Anticipate an allowance to repair sections of the irrigation system or higher cost components such as clocks and backflow prevention devices.

Trees/Vegetation - Replace (partial)

Quantity	1 Allowance
Asset Cost	\$20,000.00
Percent Replacement	100%
Future Cost	\$24 265 08

Landscape and Equipment	
Placed in Service	January 2017
Useful Life	10
Replacement Year	2027
Remaining Life	7



Trees and vegetation are mature and appear in overall good condition. Funding is for ongoing replacement of trees and vegetation due to winter kill and disease. We recommend consulting with a licensed arborist prior to tree replacements.

Pond Dam Walls - Maintain

Quantity 1 Allowance
Asset Cost \$125,000.00
Percent Replacement 100%
Future Cost \$169,369.14

Ponds and Lakes
Placed in Service
Useful Life
Replacement Year
Remaining Life
Ponds and Lakes
January 2016
2031
11







The community is responsible for (3) lake earthen dam walls within the retention lake system. Homogenous wall systems are typically constructed of a compacted clay core set in an earthen dam, and then covered with vegetation to reduce erosion. Some dam areas have been renovated in recent years. Fill and compact eroded areas to maintain dam integrity. There are several products available to prevent erosion; increased funding may be needed if these products were used.

Ponds - Clean/Maintain

Quantity 5 Each
Asset Cost \$100,000.00
Percent Replacement 50%
Future Cost \$118,020.84

Ponds and Lakes
Placed in Service
Useful Life
Replacement Year
Remaining Life
Ponds and Lakes
January 2016
2026
6





Silt is a combination of vegetation growth and runoff debris. Material should be removed occasionally to ensure proper lake capacity and usability. The association maintains (5) of the ponds located throughout the community that vary widely in size as well as accessibility. Allowance is to dredge and clean portions of the ponds on an ongoing basis as needed.

Storm Drainage - Maintain

Quantity 1 Allowance
Asset Cost \$2,000.00
Percent Replacement
Future Cost \$2,494.45

Ponds and Lakes
Placed in Service
Useful Life
Replacement Year
Remaining Life
Ponds and Lakes
January 2018
2028
8





Drainage is a significant issue throughout the community. Drainage swales should be cleaned regularly and rip-rap replaced as needed. Areas should be inspected following each major weather event. Funding anticipates future projects to maintain the systems in proper working order.

BBQ Equipment - Replace

Quantity 6 Each
Asset Cost \$1,650.00
Percent Replacement 50%
Future Cost \$1,650.00

General Common Area
Placed in Service January 2010
Useful Life 10
Replacement Year 2020
Remaining Life 0





BBQ inventory includes (6) locations at the Ridge View Park trail area, with (4) missing or broken. Funding anticipates an allowance to replace items as needed and as the Board sees fit, with no anticipation of replacing all items at one time.

Park Furnishings - Replace (partial)

Quantity 6 Each
Asset Cost \$2,550.00
Percent Replacement 50%
Future Cost \$2,550.00

General Common Area

Placed in Service January 2010
Useful Life 10
Replacement Year 2020
Remaining Life 0









Park furnishings consist of: (6) concrete picnic tables with benches with concrete pads. Furnishings range from overall fair to poor condition with some broken or missing benches. Equipment should be replaced as needed and inspected regularly. Concrete pads should be repairs in conjunction with table replacement when necessary. Funding anticipates replacing approximately 50% of the furnishings per cycle due to use and vandalism.

Gravel Walking Trail - Refurbish (partial)

Quantity 1 Allowance
Asset Cost \$2,000.00
Percent Replacement
Future Cost \$2,113.57

General Common Area
Placed in Service January 2012
Useful Life 10
Replacement Year 2022
Remaining Life 2



The gravel walking trail at Fossil Ridge Park is in overall fair to poor condition with extensive areas of cracking. Recommend repairing any trip/fall hazards immediately and inspect regularly for any damage. Funding is to repair sections as needed, with no anticipation of replacing all of the trail at one time.

Concrete Trail - Refurbish (partial)

Quantity 9,100 GSF
Asset Cost \$5,915.00
Percent Replacement 10%
Future Cost \$6,250.88

General Common Area

Placed in Service January 2017
Useful Life 5
Replacement Year 2022
Remaining Life 2



Concrete trail at Ridge View Park is in overall fair condition with areas of cracking and chipping. There was a large amount of erosion noted, where the subsurface soil had washed away. These areas should be filled regularly to prevent cracking and collapse of concrete sections. Recommend repairing any trip/fall hazards immediately and inspect regularly for any damage. Repair and replace concrete to mitigate any subsurface moisture which will accelerate deterioration. Funding is to replace sections of concrete as needed, with no anticipation of replacing all concrete at one time. Funding anticipates replacing approximately 10% per cycle.

Wood Bridges - Repair

Quantity 1,250 GSF
Asset Cost \$34,375.00
Percent Replacement 100%
Future Cost \$38,389.74

General Common Area
Placed in Service January 2014
Useful Life 10
Replacement Year 2024

Remaining Life 4







The wood bridges at the Ridge View Park walking trail appear in overall fair condition with slight fading and damage to the wood surface noted. Recommend regular staining or painting to protect wood, and periodic inspection to secure loose components. Anticipate eventual replacement of the wood deck and some structural components due to use and exposure to the elements.

Concrete Parking - Replace

Quantity 25,000 GSF
Asset Cost \$26,250.00
Percent Replacement 10%
Future Cost \$26,250.00

Placed in Service January 2015
Useful Life 5
Replacement Year Remaining Life 0







The concrete parking at the Ridge View Park and clubhouse area is in poor condition with areas of cracking and surface deterioration, but no pot holes or depressions. Surface integrity is critical to mitigate any subsurface moisture which will accelerate deterioration. Funding is to replace approximately 10% of the concrete on a regular basis.

Concrete Sidewalks - Replace

Quantity 1 Allowance
Asset Cost \$3,000.00
Percent Replacement
Future Cost \$3,000.00

	Concrete
Placed in Service	January 2015
Useful Life	5
Replacement Year	2020
Remaining Life	0



Limited sidewalks are located at the Ridge View Park and Lake Ridge walking trail areas. Sidewalks average from good to fair condition with some areas of cracking. Surface integrity is critical to mitigate any subsurface moisture which will accelerate deterioration. Funding is to replace portions of the concrete on a regular basis.

PART IV GENERAL INFORMATION

Implementing your Study (A Board's Planning Tool)

Your Reserve Study results may be simple or complex. In most cases, the results require a minor adjustment to the contribution, often offset by the reclassification of work from the operating budget to the reserve budget. In some cases, however, the reserve study results can be complex, requiring the development of a *strategic plan* that may take several years to implement.

In either case, communication is the key. Most Association Members are aware of the strengths and weaknesses of their community, even if they are never publicly discussed. We have found very little resistance to even the most difficult plans if communicated properly.

Generally, the Board can successfully implement the study in these four easy steps:

Step 1: Board Meeting

The Board of Directors has the responsibility to do what is in the best interest of the Association and has significant influence; therefore, the first step is for the Board to meet. This meeting should discuss the results of the reserve study. Invite the Association Manager to attend. The purpose of this meeting should be for the Board to better understand the financial position and the upcoming reserve requirements of the Association. This includes understanding what most influences the results of the Reserve Study

Step 2: Make a Plan

The Board should then create a plan to determine how best to manage the Association's common area assets and financial position. Using this Reserve Study as a guide, the Board should make the adjustments required to meet the needs of the Association and its members. This includes setting the Reserve Contribution amount.

Step 3: Association Meeting

After the Board has determined the best course of action, present it to the Association. This allows them to ask questions and understand the direction the community will be heading. This is by far the most important step. Communicating with owners the reasons why will help significantly. Additionally, this brings confidence in the leadership of the Board and unity among the Association members.

Step 4: Update and Adjust

This Reserve Study is a one-year document. It needs to be updated and adjusted annually. Additionally, we recommend regular reviews of your plan. Assess progress and make adjustments as necessary. As already mentioned, we recommend communicating regular updates to the Association members. Whether a major project is underway or postponed for various reasons, the membership will appreciate the update. The purpose of this Reserve Study is to help your community succeed. That only works when you are proactive and consistent.

There are 4 keys to implementing your plan effectively:

- be persistent
- make incremental changes
- monitor & implement your plan continuously
- keep your eye on the ball

Consistently using these keys will help you follow your plan and achieve your goals.

Tips for Presenting the Results

Often, the Association Members will be presented with bad news in the form of significant increases or special

assessments. In our experience, it is best to have an impartial party, such as your Reserve Provider present the results. This allows the facts to be presented without having to deal with blame or accusations of delivering an "agenda". If you wish to proceed on your own, this outline has been successful:

- Be positive! A positive, energetic presentation will help to reduce stress
- Clearly explain the reserve process
- Highlight the concepts of "fairness" and "paying for what is being used" rather than referring to component replacements as future purchases
- Highlight the concept of ongoing deterioration. There's nothing anyone can to do stop it!
- Explain how you got to your position without pointing fingers
- Assure the Members that you are on the right path
- Remember, there's only 3 ways to pay for reserve projects: increase in dues; special assessments or a loss in value due to deferred maintenance. One of the three must be met.

General Information and Answers to Frequently Asked Questions

Why is it important to perform a Reserve Study?

As previously mentioned, the reserve allocation makes up a significant portion of the total monthly dues. This report provides the essential information that is needed to guide the Board of Directors in establishing the budget in order to run the daily operations of your association. It is suggested that a third party professionally prepare the Reserve Study since there is no vested interest in the property. Also, a professional knows what to look for and how to properly develop an accurate and reliable component list.

After we have a Reserve Study completed, what do we do with it?

Step 1: Board Meeting

The Board of Directors has the responsibility to do what is in the best interest of the Association and has significant influence; therefore, the first step is for the Board to meet. This meeting should discuss the results of the reserve study. Invite the Association Manager to attend. The purpose of this meeting should be for the Board to better understand the financial position and the upcoming reserve requirements of the Association. This includes understanding what most influences the results of the Reserve Study

Step 2: Make a Plan

The Board should then create a plan to determine how best to manage the Association's common area assets and financial position. Using this Reserve Study as a guide, the Board should make the adjustments required to meet the needs of the Association and its members. This includes setting the Reserve Contribution amount.

Step 3: Association Meeting

After the Board has determined the best course of action, present it to the Association. This allows them to ask questions and understand the direction the community will be heading. This is by far the most important step. Communicating with owners the reasons why will help significantly. Additionally, this brings confidence in the leadership of the Board and unity among the Association members.

Step 4: Update and Adjust

This Reserve Study is a one-year document. It needs to be updated and adjusted annually. Additionally, we recommend regular reviews of your plan. Assess progress and make adjustments as necessary. As already mentioned, we recommend communicating regular updates to the Association members. Whether a major project is underway or postponed for various reasons, the membership will appreciate the update. The purpose of this Reserve Study is to help your community succeed. That only works when you are proactive and consistent.

There are 4 keys to implementing your plan effectively:

- be persistent
- make incremental changes
- monitor & implement your plan continuously

• keep your eye on the ball

Consistently using these keys will help you follow your plan and achieve your goals.

How often do we update or review the Reserve Study?

Unfortunately, there is a misconception that these reports are good for an extended period of time since the report has projections for the next 30 years. Just like any major line item in the budget, the Reserve Study should be reviewed each year before the budget is established. Invariably, some assumptions have to be made during the compilation of this analysis. Anticipated events may not materialize and unpredictable circumstances could occur. Deterioration rates and repair/replacement costs may vary from causes that are unforeseen. Earned interest rates may vary from year to year.

These variations could alter the content of the Reserve Study. Therefore, this analysis should be reviewed annually, and a property inspection should be conducted at least once every three years.

Is it the law to have a Reserve Study conducted?

The Government requires reserve analyses in approximately 20 States. Even if it is not currently governed by your State, the chances are very good that the documents of the association require the association to have a reserve fund established. This doesn't mean a Reserve Study is required, but how are you going to know you have enough funds in the account if you don't have the proper information? Some associations look at the reserve fund and think that \$50,000 is a lot of money and they are in good shape. What they don't know is that the roof is going to need to be replaced within 5 years, and the cost of the roof is going to exceed \$75,000. So while \$50,000 sounds like a lot of money, in reality it won't even cover the cost of a roof, let alone all the other amenities the association is responsible to maintain.

What is a "Reserve Component" versus an "Operating Component"?

A "Reserve" component is an item that is the responsibility of the association to maintain, has a limited useful life, predictable remaining useful life, typically occurs on a cyclical basis that exceeds 1 year, and costs above a minimum threshold amount. An "Operating" expense is typically a fixed expense that occurs on an annual basis. For instance, minor repairs to a roof for damage caused by high winds or other weather elements would be considered an "Operating" expense. However, if the entire roof needs to be replaced because it has reached the end of its life expectancy, then the replacement would be considered a reserve expense.

What are the gray areas of "maintenance" items that are often seen in a Reserve Study?

One of the most popular questions revolves around major "maintenance" items, such as painting the buildings or seal coating the asphalt. You may hear from your accountant that since painting or seal coating is not replacing a "capital" item, then it cannot be considered a Reserve issue. However, it is the opinion of several major Reserve Study providers that these items are considered to be major expenses that occur on a cyclical basis. Therefore, it makes it very difficult to ignore a major expense that meets the criteria to be considered a reserve component. Once explained in this context, many accountants tend to agree and will include any expenses, such as these examples, as a reserve component.

What happens during the Property Inspection?

The Property Inspection was conducted following a review of the documents that were established by the developer identifying all common area assets. In some cases, the Board of Directors at some point may have revised the documents. In either case, the most current set of documents was reviewed prior to inspecting the property. In addition, common area assets may have been reported to Community Association Reserves by the client, or by other parties.

Estimated life expectancies and life cycles are based upon conditions that were readily accessible and visible at the time of the inspection. We did not destroy any landscape work, building walls, or perform any methods of intrusive investigation during the inspection. In these cases, information may have been obtained by contacting the contractor or vendor that has worked on the property.

What is the Financial Analysis?

We projected the starting balance by taking the most recent balance statement, adding expected reserve contributions for the rest of the fiscal year, and subtracting any pending projects that will be paid for before the end of the current fiscal year. We compared this number to the ideal reserve balance and arrived at the percent funded level.

Measures of strength are as follows:

0% - **30%** Funded is considered to be a "weak" financial position. Associations that fall into this category are subject to special assessments and deferred maintenance, which could lead to lower property values. If the association is in this position, actions should be taken to improve the financial strength of the reserve fund.

31% - 69% Funded is considered a "fair" financial position. The majority of associations fall into this category. While this doesn't represent financial strength and stability, the likelihood of special assessments and deferred

maintenance is diminished. Effort should be taken to continue strengthening the financial position of the reserve fund.

70% - 99% Funded is considered a "strong" financial position. This indicates financial strength of a reserve fund and every attempt to maintain this level should be a goal of the association.

100% Funded is considered an "ideal" financial position. This means that the association has the exact amount of funds in the reserve account.

Definition of Terms Used

A reserve study contains a number of industry-related terms and phrases. To help you better understand the reserve study process and reports, we've provided definitions for the most commonly used terms.

Cash Flow Method - A method of developing a reserve funding plan where contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the anticipated schedule of reserve expenses until the desired funding goal is achieved.

Component - The individual line items in the reserve study developed or updated in the physical analysis. These elements form the building blocks for the reserve study. Components typically are: 1) association responsibility, 2) with limited useful life expectancies, 3) predictable remaining useful life expectancies, 4) above a minimum threshold cost, 5) as required by local codes.

Component Assessment and Valuation - The task of estimating useful life, remaining useful life, and repair or replacement costs for the reserve components. This task is accomplished either with or without on-site visual observations, based on the level of service selected by the client.

Component Inventory - The task of selecting and quantifying reserve components. This task can be accomplished through on-site visual observations, review of association design and organizational documents, review of established association precedents and discussion with appropriate association representative(s) of the association or cooperative.

Component Method - A method of developing a reserve funding plan where the total contribution is based on the sum of contributions for individual components. See "cash flow method".

Condition Assessment - The task of evaluating the current condition of the component based on observed or reported characteristics.

Current Replacement Cost - See "replacement cost".

Deficit - An actual (or projected) reserve balance less than the fully funded balance. The opposite would be a surplus.

Effective Age - The difference between useful life and remaining useful life. Not always equivalent to chronological age, since some components age irregularly. Used primarily in computations.

Field Inspection - A site visit which includes a visual inspection of all components. In cases where plans of the property are unavailable, it would also include the quantity survey.

Financial Analysis - The portion of a reserve study where the current status of the reserves (measured as cash or percent funded) and a recommended reserve contribution rate (reserve funding plan) are derived and the projected reserve income and expense over time is presented. The financial analysis is one of the two parts of a reserve study.

Fully Funded - 100% funded. When the actual (or projected) reserve balance is equal to the fully funded balance.

Fully Funded Balance (FFB) - Total accrued depreciation. An indicator against which actual (or projected) reserve balance can be compared. The reserve balance that is in direct proportion to the fraction of life "used up" of the current repair or replacement cost. This number is calculated for each component and summed

together for an association total. Two formulae can be utilized, depending on the provider's sensitivity to interest and inflation effects. Note: both yield identical results when interest and inflation are equivalent.

FFB = Current Cost x Effective Age/Useful Life, or

FFB = (Current Cost x Effective Age/Useful Life) + [(Current Cost x Effective Age/Useful Life) / (1 + Interest Rate) ^ Remaining Life] - [(Current Cost x Effective Age/Useful Life) / (1 + Inflation Rate) ^ Remaining Life]

Fund Status - The status of the reserve fund as compared to an established benchmark such as percent funding.

Funding Goals - Independent of methodology utilized, the following represent the basic categories of funding plan goals:

Baseline Funding - Establishing a reserve funding goal of keeping the reserve cash balance above zero.

Full Funding - Setting a reserve funding goal of attaining and maintaining reserves at or near 100% funded.

Statutory Funding - Establishing a reserve funding goal of setting aside the specific minimum amount of reserves required by local statutes.

Threshold Funding - Establishing a reserve funding goal of keeping the reserve balance above a specified dollar or percent funded amount. Depending on the threshold, this may be more or less conservative than "fully funding."

Funding Plan - An association's plan to provide income to a reserve fund to offset anticipated expenditures from that fund.

Funding Principles:

- Sufficient Funds When Required
- Stable Contribution Rate over the Years
- Evenly Distributed Contributions over the Years
- Fiscally Responsible

Life and Valuation Estimates - The task of estimating useful life, remaining useful life, and repair or replacement costs for the reserve components.

Percent Funded - The ratio, at a particular point of time (typically the beginning of the fiscal year), of the actual (or projected) reserve balance to the fully funded balance, expressed as a percentage.

Physical Analysis - The portion of the reserve study where the component inventory, condition assessment, and life and valuation estimate tasks are performed. This represents one of the two parts of the reserve study.

Remaining Useful Life (RUL) - Also referred to as "remaining life" (RL). The estimated time, in years, that a reserve component can be expected to continue to serve its intended function. Projects anticipated to occur in the initial year have "zero" remaining useful life.

Replacement Cost - The cost of replacing, repairing, or restoring a reserve component to its original functional condition. The current replacement cost would be the cost to replace, repair, or restore the component during that particular year.

Reserve Balance - Actual or projected funds as of a particular point in time that the association has identified

for use to defray the future repair or replacement of those major components which the association is obligated to maintain. Also known as reserves, reserve accounts, cash reserves. Based upon information provided and not audited.

Reserve Study Provider - An individual that prepares reserve studies.

Reserve Study - A budget planning tool which identifies the current status of the reserve fund and a stable and equitable funding plan to offset the anticipated future major common area expenditures. The reserve study consists of two parts: the physical analysis and the financial analysis.

Responsible Charge - A reserve specialist in responsible charge of a reserve study shall render regular and effective supervision to those individuals performing services which directly and materially affect the quality and competence rendered by the reserve specialist. A reserve specialist shall maintain such records as are reasonably necessary to establish that the reserve specialist exercised regular and effective supervision of a reserve study of which he was in responsible charge. A reserve specialist engaged in any of the following acts or practices shall be deemed not to have rendered the regular and effective supervision required herein:

- 1. The regular and continuous absence from principal office premises from which professional services are rendered; except for performance of field work or the presence in a field office maintained exclusively for a specific project;
- 2. The failure to personally inspect or review the work of subordinates where necessary and appropriate;
- 3. The rendering of a limited, cursory or perfunctory review of plans or projects in lieu of an appropriate detailed review;
- 4. The failure to personally be available on a reasonable basis or with adequate advance notice for consultation and inspection where circumstances require personal availability.

Special Assessment - An assessment levied on the members of an association in addition to regular assessments. Special assessments are often regulated by governing documents or local statutes.

Surplus - An actual (or projected) reserve balance greater than the fully funded balance. See "deficit."

Useful Life (UL) - Total useful life or depreciable life. The estimated time, in years, that a reserve component can be expected to serve its intended function if properly constructed in its present application or installation.

Disclosures and Limitations

Community Association Reserves has relied upon certain information provided by Association representatives in the performance of this reserve study. Such information includes, but is not necessarily limited to, financial data, identification or quantification of common area components, and historical maintenance information. Such information is deemed reliable by Community Association Reserves. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by representatives of the association, its contractors, assorted vendors, specialists and independent contractors, the Community Associations Institute, various construction pricing and scheduling manuals including, but not limited to: Marshall & Swift Valuation Service, RS Means Facilities Maintenance & Repair Cost Data, RS Means Repair & Remodeling Cost Data, National Construction Estimator, National Repair & Remodel Estimator and the McGraw Hill Book Company. Additionally, costs are obtained from numerous vendor catalogues, actual quotations or historical costs, and our own experience in the field of the preparation of reserve analysis studies.

The reserve study is a reflection of information provided to Community Association Reserves and this report has been assembled for use by the Association. This report has not been audited, nor subjected to a forensic or quality analysis, or background checks of historical records.

The reserve balance projected in this report is based upon information provided by the Association to Community Association Reserves and was not audited.

Information provided to Community Association Reserves by the Association about reserve projects is considered reliable. The on-site visit cannot be considered a project audit or a quality visit. No forensic or destructive testing was completed.

Neither Community Association Reserves, nor its owners individually have other relationships with the Association that would represent a conflict of interest.

Your Community Association Reserves, Reserve Specialist is Richard Hamilton, RS, PRA. Mr. Hamilton has been preparing reserve studies and capital budgets since 1986 and has performed hundreds of reserve studies. His reserve study experience encompasses all types of reserve studies, including condominium, townhome, master home owner, business park, resort, hotel and timeshare associations.

Mr. Hamilton holds the Reserve Specialist (RS) designation issued by the CAI, the National Community Association Institute, and is a member of the CAI. Mr. Hamilton also holds the designation of Professional Reserve Analyst (PRA) issued by the Association of Professional Reserve Analysts (APRA).

Mr. Hamilton has worked as a Controller for a large real estate investment and management firm and possesses the skills directly applicable to preparation of a financial forecast for future major repairs and replacements. The skill-set involved in the above described experience and designations represent the skills most directly applicable to evaluation of existing facilities for purposes of a reserve study.

The site visit includes observations of all visible common area components, unless otherwise indicated on the detail component listing. No destructive testing was performed.

We are not aware of any material issues which, if not disclosed, would cause a significant distortion of the

Association's reserve status or funding plan.

It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and each estimated useful life will approximate that of the norm per industry standards and/or manufacture specifications used. In some cases, estimates may have been used on assets which have an indeterminable, but potential liability to the association.

PART V MEMBER'S SUMMARY

Members Summary

POA of Lake Ridge 2020 - 2049

Number of Components Identified: 40

Fully Funded Balance Begin Fiscal Year: \$372,102.57 Reserve Fund Balance Begin Fiscal Year: \$120,100.00

Percent Fully Funded: 32%

Current Annually Contribution: \$12,000.00

Current Contribution Per Unit: \$5.68

Full (100%) Funding Annually Contribution

Recommended Contribution #1: \$58,700.00 Contribution Per Unit #1: \$27.77

Threshold (70%) Funding Annually Contribution

Recommended Contribution #2: \$54,000.00 Contribution Per Unit #2: \$25.54

Special Assessments (Annual)

Levied Year #1:

Levied Year #2:

None
Levied Year #3:

None
Levied Year #4:

None
Levied Year #5:

None

Projected Expenditures, Year #1: \$42,450.00 Projected Expenditures, Year #2: \$9,159.48 Projected Expenditures, Year #3: \$15,233.54 Projected Expenditures, Year #4: \$0.00

Projected Expenditures, Year #5: \$48,999.27

POA of Lake Ridge Member's Inventory Summary

	estix	*	2	136°	graent desc	iningo	Æ	Ç
Description	Relation of the second	Catalog Cos	25	Agi, S	ું જ્ ^{રું}	igital Co	Outrality .	Jin Cost
BBQ Equipment - Replace	2020	1,650	10	0	0	1,650	6 @	550.00
Concrete Parking - Replace	2020	26,250	5	0	0		25000 (a)	10.50
Concrete Sidewalks - Replace	2020	3,000	5	0	0	3,000	1 @	3,000.00
Deck - Restain	2020	9,000	6	0	0	9,000	2000 @	4.50
Park Furnishings - Replace (partial)	2020	2,550	10	0	0	2,550	6 @	850.00
Metal Fence/Rail - Paint	2021	8,910	8	0	1	9,159	1980 @	4.50
Concrete Trail - Refurbish (partial)	2022	5,915	5	0	2	6,251	9100 @	6.50
Exterior Masonry - Repoint	2022	4,000	10	0	2	4,227	1@	4,000.00
Gravel Walking Trail - Refurbish (p	2022	2,000	10	0	2	2,114	1@	2,000.00
Office Equipment - Replace	2022	2,500	5	0	2	2,642	1@	2,500.00
Exterior Surfaces - Repaint	2024	4,500	8	0	4	5,026	1@	4,500.00
Interior Surfaces - Repaint	2024	5,000	10	0	4	5,584	1@	5,000.00
Wood Bridges - Repair	2024	34,375	10	0	4	38,390	1250 @	27.50
Deck Substructure - Repair	2025	5,000	10	0	5	5,740	1@	5,000.00
Exterior Lighting - Replace	2025	2,500	15	0	5	2,870	1@	2,500.00
HVAC Units - Replace (partial)	2025	16,800	15	0	5	19,287	6 @	5,600.00
Miscellaneous Signs - Refurbish (part)	2025	4,000	10	0	5	4,592	1@	4,000.00
Office Carpet - Replace	2025	9,425	25	0	5	10,820	145 @	65.00
Office Deck - Replace	2025	24,650	25	0	5	28,300	2900 @	8.50
Rental Floor Carpet - Replace	2025	22,750	25	0	5	26,118	350 @	65.00
Ponds - Clean/Maintain	2026	100,000	10	0	6	118,021	5@	40,000.00
Security Equipment - Replace	2026	5,000	10	0	6	5,901	1@	5,000.00
Irrigation System - Replace (partial)	2027	15,000	10	0	7	18,199	1@	15,000.00
Trees/Vegetation - Replace (partial)	2027	20,000	10	0	7	24,265	1@	20,000.00
Storm Drainage - Maintain	2028	2,000	10	0	8	2,494	1@	2,000.00
Kitchen - Refurbish	2030	20,000	30	0	10	26,361	1@	20,000.00
Meeting Room Furniture - Replace (2030	2,700	15	0	10	3,559	1 @	2,700.00
Office Furniture - Replace	2030	3,000	15	0	10	3,954	1 @	3,000.00
Phone System - Replace	2030	7,000	30	0	10	9,226	1 @	7,000.00
Vinyl Rail Fence - Replace	2030	13,200	20	0	10	17,398	600 @	22.00
Windows/Doors - Replace	2030	52,650	40	0	10	69,395	81 @	650.00
Pond Dam Walls - Maintain	2031	125,000	15	0	11	169,369	_	125,000.00
Interior Bathrooms, Fixtures - Refur	2035	7,000	25	0	15	10,592	2 @	3,500.00
Kitchen Appliances - Replace	2035	2,500	25	0	15	3,783	1@	2,500.00
Lobby Furniture - Replace	2035	20,000	20	0	15	30,264	1@	20,000.00
Tile Flooring - Replace	2035	19,125	35	0	15	28,940	850 @	22.50
Metal Fence - Replace	2037	66,000	40	0	17	105,542	1650 @	40.00
Metal Rail - Replace	2037	11,550	40	0	17	18,470	330 @	35.00
Monument Sign - Refurbish	2039	30,000	20	0	19	50,698	1@	30,000.00
Metal Roof Roof - Replace	2057	70,200	40	0	37	195,021	3900 @	18.00